



Don Gardner
Consulting Arborist

Registered Consulting Arborist #438
Certified Arborist TX0228

**TREE CARE
RECOMMENDATIONS
FOR**

LIVE OAK GROVE

**ON FORMER
TX DOT PROPERTY
LOCATED NEAR THE
INTERSECTION OF
BULL CREEK ROAD AND 45TH STREET**

SPRING, 2015

**PRODUCED FOR
MILESTONE BUILDERS
NORRIS DESIGN**

**Produced By
Don Gardner, RCA
Registered Consulting Arborist #438
Certified Arborist TX0228**

LEGEND FOR ABBREVIATIONS USED IN THE FIELD REPORT FORMS

By Don Gardner, RCA

RV: Remove volunteers. The areas around and between the trees has been mowed using a tractor and shredder for many years. Fortunately, the mowers stayed away from the bases of trees and did not regularly hit them, which is often the case. However, in the spaces between the mowed areas and the tree trunk bases, many young sapling trees have grown. They range from one-half inch to three inches in diameter. In many instances there are so many volunteer trees and shrubs around the bases, one can barely get to the tree. The volunteer tree root systems are becoming interwoven with the large tree's root system. All of these volunteers must be removed. This work must be done carefully and sensitively.

DW: Prune dead wood two inches in diameter and larger. Pruning large dead and decayed wood minimizes and prevents larger decay in trees, prevents many structural problems from happening, and preserves the tree many more years. Proper and skilled pruning, according to International Society of Arboriculture standards, is critical to preserving trees.

Rep.: Repair is a pruning term that means to prune broken branches (usually caused by high winds) properly so the wound will close and decay will be minimized.

Train: When tree crowns grow into each other, become tangled and branches interwoven, training prunes to separate the trees so they don't constantly rub wounds and cause broken and dead branches.

Vines: Wild grape vines and poison ivy vines are not good for trees. They eventually shade out and break canopy branches.

Tree ID	Tree Species	Vigor	Structure	Rating		Maint. Task	Maint. Priority	Tree Comment	RV, DW, repair, remove low, branch over, down
				1-4	5-8				
3211	C. alnif.	L	D						
3212	C. alnif.	L	D						
3213	C. alnif.	L	O						
3215	C. alnif.	L	O						
3214	C. alnif.	L	O						
3608	C. alnif.	L	O						
3609	C. alnif.	L	O						
3216	C. alnif.	L	O						
3926	C. alnif.	L	O						
3217	C. alnif.	L	O						
3218	C. alnif.	L	O						
3925	C. alnif.	L	O						

Bull Creek Tree Care
Page 1

Don Gardner
Consulting Arborist

Tree ID	Tree Species	Vigor	Structure	Observations	Maint. Task	Maint. Priority	Tree Comment
3927	L.O						Remove. Trunk rotten
3928	Cinn.		DW, repair	DV + loop			and center rotten
3219	L.O					RV, DW, Rep	
3220	L.O					RV, DW, Rep	
3233	L.O					RV, DW, Rep	
3234	L.O					RV, DW, Rep	
3235	L.O					RV, DW, Rep	
3236	L.O		Crown with right on maturity			RV, DW, Rep.	
3238	L.O			↑ crown		RV, DW, Rep.	remove
3237	L.O					RV, DW, Rep.	ring
3241	L.O					RV, DW, Rep.	
3242	L.O					RV, DW, Rep.	
3239	L.O					RV, DW, Rep.	train
3240	L.O					RV, DW, Rep.	train
3244	L.O					RV, DW, Rep.	train
3245	L.O					DW, Rep.	train
3251	L.O					RV, DW, Rep.	ring

P#3

Tree ID	Tree Species	Vigor	Structure	Rating		Maint. Task	Maint. Priority	Tree Comment
				1-4	1-4			
3252	L0							RV, DW, Rep., Vines, train
3253	L0							RV, DW, Rep., Vines, train
3254	20							RV, DW, Rep., train
3255	L0							DV, DW, Rep.
3246	L0		1 Crown					RV, DW, Rep., train
3247	L0							RV, DW, Rep., train
3248	L0							RV, DW, Rep., train
3249	L0							RV, DW, Rep., train
3250	20							DV, DW, Rep., train
3224	L0							RV, DW, Rep., Vines
3225	L0							RV, DW, Rep., train, Vines
3226	L0							RV, DW, Rep., train


Tree ID	Tree Species	Vigor	Structure	RATING 1-4	Maint. Task	Maint. Priority	Tree Comment	
							1=dead or dying	2-poor
3221	L0						Dead - remove.	
3220	L0						R.V., DW, Rep.	
3222	L0						D.V., DW, Rep.	
3223	L0						R.V., DW, Rep., Vines	
3257	L0						R.V., DW, Rep., Vines	
3246	Sin						Remove - center leader branch	
3228	L0						R.V., DW, Rep.	
3229	L0						R.V., DW, Rep.	
3230	L0						R.V., DW, Rep.	
3227	Sin						R.V., DW, Rep.	
3258	L0						R.V., DW, Rep.	
3259	L0						R.V., DW, Rep.	

Tree ID	Tree Species	Vigor	Structure	RATING		Maint. Task	Maint. Priority	Tree Condition
				1-4	5-8			
3268	L.O						RV, DW, Rep	
3261	L.O						R.V, DW, Rep	
3262	L.O						AV, DW, Rep	
3265	L.O						R.V, DW, Rep, V. Long	
3266	L.O						AV, DW, Debark, V. Long	
3263	L.O						R.V, DW, V. Long	
3264	L.O						R.V, DW, Rep	
3268	L.O						RV, DW, Rep	
3269	L.O						AV, DW, Rep, V. Long	
3257	Osman						R.V, DW	
3295	L.D						R.V, DW, Remove broken wood, Specie to sprout	
3293	C. L.						Rep. S. and C. 2020.	

M.T. Tree Care

Bull Creek Tree Care
Page 5Don Gardner
Consulting Arborist

Tree ID	Tree Species	Vigor	Structure	RATING 1-4	Maint. Task	Maint. Priority	Tree Comment
3294	L0						RV, DW, NW, Vines elbow weak, branch age on main
3297	L0		most tree falling				NW, NW, Vsp.
3298	L0						
3299	-		most hollow				
3300	20						QV, NW, Vsp., Vines
3300	L0						RV, DW, NW, Vines
3298	L0						RV, DW, Vsp., Vines
3299	20						RV, DW, NW, Vsp., Vines
3291	L0						RV, NW, Vsp., Vines Dw, Vsp., Vines
3300	L0						



Don Gardner *Consulting Arborist*

*Registered Consulting Arborist #438
Certified Arborist TX0228*

PECANS ON THE GROVE SITE

November 7, 2015

For: AGR Bull Creek

I examined all protected trees on this entire site in February and March, 2015.

The magnificent live oak grove is a natural wonder. How can trees this old be so healthy and vigorous? Now, the job is to make sure they stay healthy. Protecting 3/4 of the critical root zone, which I've heard is proposed, is one of the ways to do that.

Most of the pecans on the site, however, are an altogether different story. They are all planted pecan varieties, not native pecans.

Orchardists have been developing new pecan varieties for decades. None are as good a tree (i.e., hardy, strong structure, long-lasting) as the old, original native varieties. Some varieties are better than others, but some are truly horrendous and should have never gotten out into the landscape market.

These varieties are not good, strong pecan trees, but are weak with multiple structural issues. They have more in common with Arizona ash trees, with notorious flaws, than with native pecan trees.

The health of a tree can go bad, or the structure can go bad.

The structural issues with the pecans in question include, 1) poor branch attachment, 2) co-dominant trunks with one trunk growing laterally, not upward, and 3) included bark that holds water, and decays easily and rapidly.

In addition, pecans have the reputation for branch breakage, which they deserve. And, it can be counted on, the newer varieties will break when they get a little size and weight on them.

Further, due to prolonged heat and drought, many of the pecans at this site, like pecans all over central Texas, have major crown dieback, with all the decay and structural issues that come with large dead wood.


Someone planted poor pecan varieties and they lasted a while. But now, the trees are coming apart. They should be removed.

Unfortunately, the pecans are not good, strong, long-lived natives like the live oaks in the groove.

Please contact me if you have any questions.



Don Gardner, RCA
Registered Consulting Arborist #438
Certified Arborist TX 0228



Don Gardner
Consulting Arborist

Registered Consulting Arborist #438
Certified Arborist TX0228

FAX

2-10-2015

13 PAGES TOTAL

To: Robert Deegan

From: Don Gardner, Consulting Arborist 

Enclosed please find the 12 pages ^{completed} evaluation forms
for the Milestone project.

Bull Creek Project 2-4-15

1=dead or dying 2-poor 3-fair 4-good

11

Tree ID	Tree Species	Vigor	Structure	RATING 1-4	Maint. Task	Maint. Priority	Tree Comment
3065	Cottonwood		2				2" necrotic carbons at base 15" high sunburst from pruning Planted 20-inches
3064	Liquid Oak		3/4				No hollow postified?
3085	Tallow		3				
3084	Tallow		3		DW repair		
3083	Tallow		3	"			
3082	C. slim		3	"			18" - not 20"
3081	Hickory		2				Trunk decay/ branch decay/ misfortune
3080	Amelanchier slim		2				Co-dom, support, crown 4000 wet wood, decay, postified
3067	Pecan		3		DW repair		
3066	Tallow		3	"			
3073	Liquidambar		33				
3072	dead oak		1				Not Distressed

Tree ID	Tree Species	Vigor	Structure	Rating		Tree Comment
				1-4	Maint. Task	
3071	Chapel Myrtle		3			18.5 inches
3070	"		3			22 inches
3068	Pecan		3/4	DW repair		
3069	Nack Henry		2			multiple co-doms, very weak structure
3073	Pecan	3	DW repair			27 nicely formed - long strong arms 45°. Open extended
3076	Pecan	3	"			Very poor structure 18" weak. Trunk will break
3074	Pecan		2			been de-thornced
3077	Pecan		2/3			over 2 ft. dead branch
3078	Pecan		3			One extended branch
3079	Pecan		3			

1=dead or dying 2-poor 3-fair 4-good

12-13

12

live tanks not on tree list

1=dead or dying 2-poor 3-fair 4-good

2-4-15 P3

Tree ID	Tree Species	Vigor	Structure	RATING 1-4	Maint. Task	Maint. Priority	Tree Comment
3283	live oak(LQ)	"	3				
3284	"		3				
3285	"		3				
3270	"		4				
3281	"		4				
3280	"		3				
3277	"		3				
3278	"		4				
3279	"		3				
3271	"		3				fire scar
3272	"		4				
3273	"		3				hole near & spot trunk bend

live oaks not on tree list

1=dead or dying 2-poor 3-fair 4-good 2-4 is P4

Tree ID	Tree Species	Vigor	Structure	RATING 1-4	Maint. Task	Maint. Priority	Tree Comment
3274	Bur oak	"	3				
3275	"		2/3				fire scar. Following trunk may be Indian marker tree
3276	"		3				fire scar - trunk closing

Tree ID	Tree Species	Vigor	Structure	Rating 1-4	1=dead or dying 2-poor 3-fair 4-good		2-4-15 P5
					Maint. Task	Maint. Priority	
3205	C.	slim	2	2			Crown full w/ misbalance
3206	"		2				storm removed crown top half much middle tree & dead with 3 new trunks - 1 w/mushroom + loose Crown much in next
3207	Pecan		2				
3208	Pecan		2				19" " hyper multiple co-domes / dead & broken branches. Perhaps mitigate
3209	Pecan		2/3				
3204	Pecan		3				
3203	Pecan		3	26"			(bottom) slender
3202	Pecan		2	26"	w/ hyper lower		
3201	Pecan		2/3	26"	Crown distorted + over extended branches		

1=dead or dying 2-poor 3-fair 4-good

P. 6

Tree ID	Tree Species	Vigor	Structure	RATING 1-4	Maint. Task	Maint. Priority	Tree Comment	1-6-15
3211	C elm	L O		2/3			Pruned mistletoe + old storm breakers	
3212	L O			3				31"
3213	L O			3				
3215	L O			3				
3214	C elm	L O		3/4			Lightning strike clearing heat tree	
3216	L O			3			28" Big storm break	
3218	L O			3				
3217	L O			3/4				30" FAB
3925	16" L O			3				
3926	18" L O			3/4			Inward	
3220	L O			3/4				
3233	L O			3/4			33" Intri' Pori' rivity	

1=dead or dying 2-poor 3-fair 4-good

P-7
2-6-15

Tree ID	Tree Species	Vigor	Structure	RATING 1-4	Maint. Task	Maint. Priority	Tree Comment
3234	LO			3/4			
3235	LO			3			
3238	LO			3/4			
3237	LO			3/4			
3243	LO			3			
3239	LO			3			
3240	LO			3			
3241	LO			3/4			
3242	LO			3/4			
3236	LO			3	FAB		
3226	LO			3/4	2.5" side stem absent count in DBH		
3225	LO			4	Two trunks 50" + dbh FAB		

1=dead or dying 2-poor 3-fair 4-good

P 9

Tree ID	Tree Species	Vigor	Structure	RATING 1-4	Maint. Task	Maint. Priority	Tree Comment
3255	L0			3			22" wide strong trunk
3257	L0			3/4			60" diameter trunk
3257	C elm			2	Poor form		3 Trunks low scaffold broken tops few scattered decaying stn main leader broken at 12"
3258	C elm			2			decaying.
3221	L0			1			
3219	L0			3/4			old split near cavity closing
3210	L0			3			Big scaffold break
3222	L0			3			old live near cavity
3223	L0			3/4			35" not counting big scaffold
3228	L0			3			30" + crown thin broken
3229	L0			3/4			
3230	L0			3/4			

Tree ID	Tree Species	Vigor	Structure	RATING 1-4		Maint. Task	Maint. Priority	1=dead or dying 2-poor 3-fair 4-good	Tree Comment	P 8 26-13
				Maint.	Task					
3224	L0			3						
3244	L0			3/4						
3251	L0			1/3						
3252	L0			3/4						
3253	L0			3						
3245	L0			4						
3247	L0			3/4						
3246	L0			3/4						
3248	L0			3/4						
3249	L0			3/4						
3250	L0			3/4						
3254	L0			3/4						

3 together

are around

1=dead or dying 2-poor 3-fair 4-good 2-9-15 P.I.D

Tree ID	Tree Species	Vigor	Structure	RATING 1-4	Maint. Task	Maint. Priority	Tree Comment
3232	Pecan		2/3				poor vgy! poor structure
3231	Pecan		2				18"-19" active decay at co-dom branch
3258	LO		3				
3259	LO		3				
3265	LO		3				2 trunks 50+ inches pecan vgy
3266	LO		3				
3263	LO		3				
3262	LO		3				
3261	LO		3				
3260	LO		3				
3264	LO		3				
3267	Cedar (purple)		3				

P11
1=dead or dying 2-poor 3-fair 4-good

2-9/15

Tree ID	Tree Species	Vigor	Structure	RATING 1-4	Maint. Task	Maint. Priority	Tree Comment
3296	Spurce	N	2				
3297	Spurce	11	2				
3100	"	"	2				DW, Decay
3200	LO		3				
3298	LO		3				
3208	LO		3				
3289	LO		1-2				return tree int up
3290	LO		3				
3291	LD		3				
3292	LO		35"				Homeless
3287	LO		40"				Camp

Tree ID	Tree Species	Vigor	Structure	RATING 1-4		Maint. Task	Maint. Priority	Tree Comment	1=dead or dying 2-poor 3-fair 4-good	
				Maint.	Task				Priority	Date
3294	LO			3				old girdled tree main leader dead, lower my T		P12 2-9-15
3293	C. LO			2				CD - long poison ivy large scaffold break		
3295	LO			3						
3268	LO			3/4						
3269	LO			3				poison ivy		

